


# XP800

----- Overall dimension

————— Cutout line



## INSTRUCTIONS:

- 1) **WARNING!!** Drawing should not be scaled. Prior to drilling, please verify the dimensions of the print out.
- 2) Drill  $\phi 12$  first and then proceed with rest of the drillings